MATERIAL SAFETY DATA SHEET

H	<u> 2</u>	
F	1 0	•
R	. 0	•
P	В	•

SECTION I - PRODUCT IDENTIFICATION

TRADE NAME: SAKRETE MORTAR MIX

CHEMICAL FAMILY/SYNONYMS: Portland Cement Mortar, lime, silica

MANUFACTURER: W. R. BONSAL COMPANY, P.O. BOX 241148, CHARLOTTE, N. C. 28224

EMERGENCY PHONE: (704) 525-1621 Mr. Fred Goeman

SECTION II - HAZARDOUS INGREDIENTS

DESCRIPTION	N CAS #	PERCENT	1	OCCUPAT EXPOSURE TLV	IONAL	VAPOR PRESSURE (MM HG)
PORTLAND CEMENT LIMESTONE GYPSUM SILICA SAND *	65997-15-1 1317-65-3 13397-24-5	11-15 8-10 4-5	15	mg/m³ mg/m³	15 mg/m³	N/A
RESPIRABLE DUST AMORPHOUS SILICA	14808-60-7 60676-86-0	80 - 75 0-3		mg/m³	0.1 mg/m³	N/A

* % is determined from air borne samples.

NOTE: Previous air monitoring during employee exposure to this product has indicated typical airborne respirable quartz fractions of up to 3%.

SECTION III - PHYSICAL DATA

BOILING POINT (°F) N/A	SPECIFIC GRAVITY (H,0=1)	-
VAPOR PRESSURE (mmHg.) N/A	& MALIETTE DA MARIETT	<u>2.6 2.7</u>
	% VOLATILE BY VOLUME (%)	0
VAPOR DENSITY (AIR=1) N/A	EVAPORATION RATE	N/A
SOLUBILITY IN WATER: Slight (0.1-1.	.0%)	_0./ 63

APPEARANCE & ODOR: Fine, grey powder mixed with sand and/or rock, no odor.

SECTION IV - FIRE & EXPLOSION HAZARD DATA -----

FLASH POINT: Will not ignite FLAMMABLE LIMITS N/A

EXTINGUISHING MEDIA: None

SPECIAL FIRE FIGHTING PROCEDURES: None

UNUSUAL FIRE AND EXPLOSION HAZARD: None

Page 1 of 2

APR-96

Prepared By: Priedrich Goeman

116

MATERIAL SAFETY DATA SHEET PRODUCT: SAKRETE MORTAR MIX

SECTION V - HEALTH HASARD DATA

THRESHOLD LIMIT VALUE: Respirable Dust - PEL = 0.1 mg/m3

EFFECTS OF OVEREXPOSURE: Excess exposure by inhalation over an extended period of time may result in the development of pulmonary diseases including pneumoconiosis and silicosis. Prolonged contact can produce skin irritation and dermatitis. Abrasive, skin and eye irritant.

EMERGENCY FIRST AID: Inhalation: remove from exposure. If not breathing, give artificial respiration, if breathing difficult, give oxygen, consult a physician. Bye Contact: flush thoroughly with water for 15 minutes.

Consult a physician. Skin Contact: wash thoroughly with soap and water.

Consult a physician. Skin Cont	act: wash thoroughly with soap and water.	
SECTION VI - REACTIVITY DATA		
STABILITY: CONDITIONS TO AVOID: N/A	UNSTABLE STABLE _X	
SECTION VI	- SPILL OR LEAK PROCEDURES	
to prevent dust exposures and pre-	SPILLED: Use personal protective equipment otect against alkali burns or irritation. Sec. 8. of in accordance with Federal, State and	
	SPECIAL PROTECTION INFORMATION	
	NIOSH/MSHA approved for protection against	
Local Exhaust: Yes	Special:	
Mechanical:	Other:	
PROTECTIVE GLOVES: RUBBER, FVC, OTHER PROTECTIVE EQUIPMENT: Rubb to prevent skin contact.	Neoprene EYE PROTECTION: Goggles er boots, arm sleeves and aprons when necessary	
SECTION	IX - SPECIAL PRECAUTIONS	
PRECAUTIONS IN HANDLING AND STOR	ING: Store in manner to prevent contact with	

Page 2 of 2

strong acids. Avoid contact with water to preserve product.

OTHER PRECAUTIONS: None